	rjngroup										Name	
	Excellence through Ownership					es for Sanitary Sewer System			BPA01 City MH I.D.			
	Sewershed PATAPSCO		Projec		_	Inspection Date/Time 12/15/2005			S39E2_0			
			995R			Inspected By			hole	ole Pipe		
						JM/JS		Depth (ft)	Width (ft)	Width (in)	Height (in)	
	Site Address:			4116 TO	OWNSEND			13.62	2.00	15.00	15.00	
	MH Type: Brick Pr	Pipe Type:	O Brick	O Concrete	Clay	Other	Pipe Shape:	Circular	Овох	Odd		
	Top View Pi	icture	Area L				a Location Map			Safety Concerns		
SITE INVESTIGATION				O Ave W Pelapsco Ave Hustor Transit Tr					Gas			
									● U/S ○ D/S	1 ft		
Z			Brooklyn Park Barbara				Brook Park	Manhole Coordinates				
ITE	Area View Picture			Urcohyn Park. Vicinity Map			20,01	TO THE MAN		569,123.50 N		
PART A - SI								(171)	1,424,828.26 W Telog Antenna Installation			
	Area view Ficture			Vicinity Map			T COM	The state of the s	Asphalt			
							N		✓ Concrete	☐ Traffi		
								Signal Strengt		25%		
							Mr. C.	Telog Phone # (410) 215-9122				
				; joru					System Characteristics			
				3	WAS END AN SOURCE TO 194794			and the	✓ Residential			
	4			ST.	Town				Commercial			
	L Industrial											
	Hydraulic Assessment											
	Surcharge (ft): 0.00											
	Flow Depth (in): 3.88 Instant Vel (fps): 1.67						Silt Level (in): 0.00 Signs of I/I: roots					
	HYDRAULIC RATING: O A (good)				B (questionable) C (or)	Recomme Install		Yes No	
									Meter Ty	pe: ADS-F	lowShark	
SITE INSTALLATION	Installation Plan Sketch					Installation Profile Sketch						
	15"					U V					FAKI B. SILE INSTALLATION	
CALL	23										9-91	
INST	Installation Information								Installation	on Photo	į.	
TE]			Incor		1 .	Outgoing	OF	1				
PART B - SI	Line #	<u>1</u>	2	3	4	15.00	1					
	Size (in) Material	m e				VCP						
	Debris (Y/N)	t				N		W				
	Shape	e				Cir.						
	Flow Depth (in):	r				3.88						
	Instant. Vel. (fps)					1.67		V .				
	Comments:					<u>'</u>		May 1				